

# Balancer Adapterboard Universal

FR - Notice d'assemblage

GB - Instruction

Réf.  
Ord. No. 15 3043



FR

GB



Si vous avez des questions au sujet de la déclaration de conformité, veuillez vous adresser à :

**Jamara e. K.**  
**Inh. Manuel Natterer**  
**Am Lauerbühl 5**  
**DE-88317 Aichstetten**  
 Tel. +49 (0) 7565/9412-0  
 Fax +49 (0) 7565/9412-23  
[www.jamara.com](http://www.jamara.com) - [info@jamara.com](mailto:info@jamara.com)

D'autres informations sous :  
[www.neuershop.jamara.com/Conformite](http://www.neuershop.jamara.com/Conformite)



Veillez à respecter les consignes de recyclage des appareils électroniques (radiocommande, chargeur ou modèle, ...) en fonction des directives en vigueur. Jetez uniquement ceux-ci dans les poubelles les bacs de ramassages que vous trouverez dans les magasins ou dans votre commune.

## Descriptif général

Du fait que la société Jamara ne peut ni contrôler le respect des consignes d'assemblages, d'entretien et d'utilisations de votre appareil, celle-ci ne garantie en aucun cas la perte, les dégâts ou coût pouvant résulter d'une utilisation non conforme.

En accord avec les textes de lois relatif aux dommages et intérêts, nous limitons le montant en fonction du montant facturé du produit concerné lors de votre achat. Cela n'est pas valable en fonction de négligences ou autres actions non prévues dans les textes de lois et listés ci-dessus.


## Instructions

**Prêtez attention à polarité correcte et n'utiliser qu'un seul connecteur par charge LiPo!**

- 1 Connecteur 2S – 6S pour ThunderPower / FlightPower Multiplex
- 2 Connecteur 2S – 6S pour Poly-Power / Align
- 3 Connecteur 2S – 6S pour Hyperion / PolyQuest
- 4 Connecteur 2S – 6S pour Robbe / Graupner / Kokam
- 5 6S Connecteur pour balancer connecteur de chargeurs de différents fabricants.
- 6 pôle négatif (1er à gauche)
- 7 Espace libre pour des plug-in système

### Seulement pour les constructeurs de modèles expérimentés:

Sur le connector gratuit lieu peut demander un connector custom système pouvant être brasée. Retirez la mousse ou de l'isolation sur le dos de la carte de balancier de la région et souder les contacts appropriés. Isoler le joint de brasure avec l'isolation / mousse à nouveau.



Please direct any queries that you may have to our service department at:

Jamara e. K.  
 Inh. Manuel Natterer  
 Am Lauerbühl 5  
 DE-88317 Aichstetten  
 Tel. +49 (0) 7565/9412-0  
 Fax +49 (0) 7565/9412-23  
 www.jamara.com - info@jamara.com

Weitere Informationen finden Sie auch unter:  
 www.jamara.com



Please dispose of any part of this unit correctly, observing local regulation regarding the disposal of electrical waste. In most cases such waste must be placed into a dedicated collecting container for disposal.

## General Instructions

As the company JAMARA e.K. has no influence over the use, maintenance or conditions under which this product will operate, we accept no responsibility for any damage caused by it of a physical, financial or theoretical nature which results directly or indirectly from the operation or use of its products.

Any claim arising from our supplying of or the operation of our products will not be met. Any claim regarding our Products will cover exclusively and solely our product. This will not apply if legal reasons dictate, or in a case where Gross negligence on our part can be legally proved.


## Instruction

**Watch out for correct polarity and use only one slot per LiPo charge!**

- 1 Connector 2S – 6S for ThunderPower / FlightPower Multiplex
- 2 Connector 2S – 6S for Poly-Power / Align
- 3 Connector 2S – 6S for Hyperion / PolyQuest
- 4 Connector 2S – 6S for Robbe / Graupner / Kokam
- 5 6S connector for balancer wire to plug chargers from different brand.
- 6 minus Pole (1. from left)
- 7 free plug-in place for custom plug system


### Only for experienced model builders:

On the free plug-in place can request a custom plug-in system to be soldered. In addition, remove the foam / insulation on the back of the balancer-card into the appropriate area and solder the contacts. Then isolate the solder joints with the removed insulation / foam again.



# Bon

# Coupon



Demandez encore aujourd'hui notre catalogue principal  
actuel présentant nos différentes gammes de produits.

Order the current catalogue with our complete  
assortment of modelling goods today.

Nome \_\_\_\_\_  
Prénom \_\_\_\_\_  
Adresse \_\_\_\_\_  
Ville \_\_\_\_\_  
Téléphone \_\_\_\_\_  
E-mail \_\_\_\_\_

Name \_\_\_\_\_  
First name \_\_\_\_\_  
Street \_\_\_\_\_  
City \_\_\_\_\_  
Phone \_\_\_\_\_  
E-mail \_\_\_\_\_

Veillez envoyer mon catalogue à mon revendeur habituel:

Please send the catalogue to the following specialist  
dealer:

Revendeur  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Your dealer  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Veillez envoyez mon catalogue avec mon nom à mon re-  
vendeur lors de sa prochaine commande.

We will include a catalogue for your attention with the  
next order placed by your dealer.